

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CC395
NNE
1/2-1
0.637 mi.
3362 ft.

GAS STATION
AVE Y/W. 3RD ST SE CORN
BROOKLYN, NY

NY Spills **S102663432**
N/A

Site 1 of 5 in cluster CC

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: GAS STATION
Address: AVE Y/W. 3RD ST SE CORN
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9705437 / 1997-08-05
Facility ID: 9705437
Facility Type: ER
DER Facility ID: 150547
Site ID: 179378
DEC Region: 2
Spill Cause: Other
Spill Class: E5
SWIS: 2401
Spill Date: 1997-08-05
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1997-08-05
CID: 370
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-08-05
Spill Record Last Update: 1997-08-06
Spiller Name: Not reported
Spiller Company: GAS STATION
Spiller Address: AVE Y/ W. 3RD ST SE CORN
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG REFERRED TO ECO."
Remarks: "WHEN GAS STATION GETS FUEL DELIVERY THEY OPEN UP CAPS ON OTHER SIDE OF TANKS AND CALLER STATES FUMES TRAVEL 1/2 BLAOCK TO HIS RESIDENCE STATES FUMES ARE VERY BAD AND WAKES HIM UP IN THE NIGHT AND HE HAS TO LEAVE WHEN THIS IS GOING ON USUALLY LASTS FOR 30 MIN MR TANG (DEC) IS AWARE OF THIS ALREADY"

All Materials:

Site ID: 179378
Operable Unit ID: 1051431
Operable Unit: 01
Material ID: 334653
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported